


Circuit:	<u>GP</u>	Document No.	<u>01</u>
Championship:	<u>UAE PROCAR SERIES</u>	Date:	<u>04/12/2020</u>
		Time:	<u>10:30</u>

The Stewards have considered the following matter and determined the following:


Driver No. & Name	#7 FAHAD AL ZAABI
Entrant	
Session	QUALIFYING
Time	09:30
Situation/Fact	REPAIRS TO ROLLAGE UNSAFE
Offence	TECHINICAL / SAFETY BREACH
Decision	VEHICLE DISQUALIFIED FROM COMPETITION
Reason	VEHICLE UNSAFE DUE TO BENT ROLL CAGE TUBE. MUST BE REPLACED AND REPRESENTED FOR SCRUTINEERING.



Chairman of the Stewards
 Alqassim Hamdallah



Steward J. DONCASTER



Steward G. SHEFFIELD

Acceptance of the penalty by
 concerned driver
 (if driver was heard):

Cristian Bermudez
 Name



Signature

NGK UAE PROCAR Championship Infringement Sheet

Date: 04-12-2020	Event: NGK -01-
Time: 9:53-27	Car No: 20

Code	Description of Infringement	
11.2	Driving through a red light at pit exit	
12.3	Race Start from pit exit – car did not get to pit exit under its own power	
12.4	Use of tyre heating/heat retention devices, tyre treatment and compounds on the grid	
12.5(a)	Grid – Engines not started at 1 minute	
12.5(b)	Grid – Grid not cleared at 15 seconds	
15.3	Refuelling in the working lane	
15.4	Car with internal filler being refuelled with the driver still in the car	
17.9	Car driven unnecessarily slowly, erratically or dangerously in Pit Entry or the Pit Lane	
18.2	Cars driven back to garage at the end of race and not to Parc Ferme	✓
18.4	Helmet and harnesses removed before car stationary in pit lane	
22.3	Exceeding pit lane speed limit (60kph)	
22.4	Fire extinguishers not present during refuelling	
22.5	Children under 13 years old in the pit lane	
22.6	Competitors painting lines in the pit lane	
22.7	Driving into garage forwards under own power, not pushed backwards into garage	✓
22.8	Not clearing pit lane in a safe and timely manner keeping clear for next races	
23.4	Working on car whilst stationary as a result of a time penalty	
30.3	Alcohol/Tobacco advertising shown	
	Driving in wrong direction or reversing in pit lane	
	Jump start or causing false start	
	Failure to push car back into garage or obstruction of pit lane	
	Physical or verbal abuse of an official or failure to obey instructions by marshals	
	Unsafe release	
Additional Comments		
Driver - drive back to the box (Engine power)		

Marshal Name

Sultan Alnas #004833

Date

04-12-2020

Marshal's Signature

Chief/Deputy Pit Signature